Revision Summary

The table bellows contains important changes made in the September 1, 2015 revision of the *Construction Performance Guide for New Home Warranty in Alberta*.

Page	Entry	Revision
All pages		Changed edition date to September 1, 2015
p. 15		Clarification of applicable version of Guide
pp. 18-19		Content change regarding "Walk-Through Inspection"
p. 19		Removed paragraph discussing owner-supplied design, materials, and labour
p. 74	3.8	Added reference to walk-through inspection
p. 82	4.1	Updated claim response
p. 105	5.7	Added reference to walk-through inspection
pp. 106 -	5.8	Split 5.8 into two separate entries (5.8 and 5.9)
107		
p. 120	5.22	Added normal lighting/viewing position text; removed mention of builder or
		builder's trades
p. 124	5.26	Added reference to walk-through inspection
p. 146	6.18	Added reference to walk-through inspection
p. 147	6.19	Removed "steel skin" from Remarks section
p. 153	6.25	Added reference to walk-through inspection
p. 155	6.27	Added reference to walk-through inspection
p. 158	6.30	New entry on mould and mildew
p. 159	7.1	Fixed conversion error in Acceptable Performance Condition
p. 169	7.11	New entry on gaps in vinyl siding
p. 182	7.24	Added reference to walk-through inspection
p. 183	7.25	Minor revisions to align with new entry 6.30
p. 185		Fixed formatting error to split chapter 7 into two chapters
p. 197	9.1	Added reference to walk-through inspection
p. 233	11.10	Removed "in spots"; added reference to walk-through inspection
p. 245	13.1	Added reference to walk-through inspection
p. 247	13.3	Added reference to walk-through inspection
p. 255	14.7	Added reference to walk-through inspection
p. 294	16.14	Added reference to walk-through inspection
p. 320	17.16	Removed mention of "builder or builder's trades" in Claim Response
p. 327	17.22	New entry on radon